NSPIRE CTQ Inside Health and Safety						
Version	Inspectable Item	Deficiency	Life-Threatening H&S	Severe Non-Life- Threatening H&S	Standard H&S	
1.3	Auxiliary Lighting	Auxiliary lighting fails to illuminate when tested  Auxiliary lighting damaged or missing			X X	
1.3	Bathroom Ventilation	1. Bathroom does not have proper ventilation			X	
1.3	Bathtubs and Showers	Bathtub or shower is missing or not installed Bathtub or shower component is damaged, inoperable, or missing Bathtub fails to retain water		X	X	
		Bathtub or shower fails to drain water			Χ	
1.3	Cabinets	Cabinet components are damaged or missing			X	
1.3	Call-for-Aid System	Cabinet case or box is damaged or loose PUII cord is missing or end is higher than 6 inches off the floor			Х	
1.3		System is blocked	X		Х	
1.3	Carbon Monoxide Detector	Carbon monoxide detector is missing, not installed, or not installed in proper location.  Carbon monoxide detector is obstructed.  Carbon monoxide detector does not produce audio or visual alarm when tested.	X X X			
1.3	Ceiling	Ceiling has sign of structural failure			X	
1.3	Chimney	Damper will not open or stay open Liner, pipe, or chimney structure has hole (any size) in it			X X X	
		Chimney surface is damaged or missing materials			Χ	
1.3	Cooking Appliance	Cooking range, cooktop, or oven is not producing heat or regulating heat temperature Cooking range, cooktop, or oven components			X	
		are missing Primary cooking appliance is missing			X	
	Door - Entry	Entry door will not open Hole, split, or crack that penetrates completely through entry door Entry door is missing	X		X	
		Entry door will not close Entry door self-closing mechanism is damaged, inoperable, or missing Entry door's primary lock is damaged, inoperable,		X	X	
1.3		missing, or not installed Entry door surface is delaminated or separated			X	
		Entry door frame, threshold, or trim is damaged or missing			Х	
		Entry door seal, gasket, or stripping is damaged, inoperable, or missing			X	
		Entry door has a broken seal thermal pane Entry door security device or secondary primary lock damaged or inoperable			X	
	Dryer Vent	Gas dryer vent is missing, detached, or has a hole Electric dryer vent is missing, detached, or has a	Х			
1.3		hole Dryer vent has restricted airflow Gas dryer vent of unsuitable material has been	X		X	
		installed			Х	
1.3	Egress	Blocked egress in a building 4 stories or more Blocked egress on building 3 stories and less	X X			
1.3	Electrical Enclosures	Electrical service panel is not readily accessible Electrical enclosure is contaminated	X		Х	
1.3	Electrical Outlets/Switches	Outlet is broken, cracked, or burned Outlet is improperly wired		X	<u>X</u>	
1.2	Elevator	Inadequate number of outlets Elevator is not operating Elevator door does not fully open or close at each			X X X	
1.3		floor Elevator cab not level with the floor Safety door or emergency phone is inoperable			X X	
		Exit sign that clearly identifies emergency exit is missing or obstructed	Х			

Version	Inspectable Item		}	}	
1.3		Deficiency	Life-Threatening H&S	Severe Non-Life- Threatening H&S	Standard H&S
	Exit Sign	Lighted exit sign does not illuminate or there is no adjacent or other internal illumination in operation on or near the sign  Exit sign that clearly identifies emergency exit is		Х	
	i	damaged	}		X
1.3	Exposed Electrical Conductor	Exposed electrical wire Door does not open, close, or latch	X	······································	
1.3	Door - Fire	Door does not self-close and latch		X	
1.5		Door surface is damaged			X
		Door seal or gasket is damaged or missing Door does not open, close, latch, or lock		X	X
1.3	Door - General	Any size hole or crack that penetrates the door into the adjacent room  Damage to the door, door frame, or case that			X
		directly impacts privacy or structural integrity			X
		Fire extinguisher pressure gauge reads over or under charged	Х		
1.3	Fire Extinguisher	Fire extinguisher service tag is missing or expired Fire extinguisher is missing	X X		
1.3	Flammable and Combustible	Improperly stored flammable or combustible item	X		
1.0	ltems	on or near an ignition source	^		
1.3	Floor, Floor Covering, and Floor Finish	Floor substrate is exposed Floor covering is curling, buckling, or bulging Subfloor is bowed, buckling, or sagging			X X X
1.3	Floor Drain	Subfloor has presence of decay Drain is clogged			X X
		Foundation infiltrated by water Foundation is cracked			X X
1.3	Foundation	Foundation has exposed rebar or foundation is spalling, flaking, or chipping Support posts, columns, beams, or girders are			X
		damaged The foundation appears to be in imminent danger of collapse or failure	X		X
1.3	Garage Door	Garage Door has Holes Door does not open, close, or remain open or			X X
		closed GFCI and AFCI test and reset buttons are			
1.3	Ground Fault Circuit Interrupter (GFCI) & Arc Fault Circuit Interrupter (AFCI)	inoperable GFCI or AFCI have broken, cracked, or burned	V		X
		surfaces, or buttons are missing	Х		
1.3	Graffiti	GFCI protection is not present where required Graffiti is present			X
1.3	Grab Bar	Grab bar is not secure			Х
	Guardrail	Guardrail is missing where required Guardrail component(s) missing	X	X	
1.3		Guardrail is not secure		•	Χ
		Guardrail is not at least 36 inches in height Handrail missing where required			X
1.3	Handrails	Handrail is not secure			X
		Handrail is improperly installed  Heating or air conditioning system or device is not			X
1.3	Heating, Ventilation, and Air Conditioning (HVAC)	operational Heating system or device fueled by combustion	X		
		has misaligned, disconnected, damaged, blocked, or missing exhaust vent	Х		
	Infestation	Evidence of cockroaches Evidence of bedbugs			X
1.3		Evidence of mice			X
1.0		Evidence of rats Evidence of other pests (insects, vermin, birds,			X
	Interior Wall Coverings and Finishes	bats) Hole is greater than 2 inches in diameter or any accumulation of holes that is greater than 6 inches			X
1.3		by 6 inches Hole that penetrates to the adjoining room or			X
		space Interior wall is buckling, bulging, or material is			X X
	With the state of	detached Countertop is missing			X
1.3	Kitchen Countertop	Countertop is missing  Countertop is damaged  Kitchen exhaust does not respond to controls			X X

Severe Non-Life-						
ersion/	Inspectable Item	Deficiency	Life-Threatening H&S	Threatening H&S	Standard H&S	
1.3	Kitchen Ventilation	Kitchen exhaust is obstructed from receiving			Χ	
		airflow  Kitchen exhaust duct is improperly installed or			χ	
	Land hand Bairt Batariini	missing				
1.3	Lead-based Paint – Potential Hazard	Paint on a target property is peeling or deteriorated			X	
	Leak	Natural gas, propane, or oil leak at the main	X			
1.3		Natural gas, propane, or oil leak at the appliance	Х			
		Blocked sewage system		Χ		
		Leak in sewage system		X		
		Environmental water intrusion Plumbing leaks			XX	
		Interior light fixture will not illuminate when			X	
	Light Fixtures (Interior)	energized (or not operational)				
1.3		Interior light fixture is not securely attached or anchored			X	
		i -			······································	
		Interior light fixture is missing in kitchen or bathroom			Х	
1.3	Litter	Litter is accumulated in an undesignated area			X	
1.3	Mold	Presence of mold or mildew is observed visually or through smell			Χ	
		Refrigerator does not cool			Χ	
1.3	Refrigerator	Refrigerator is missing where required			Χ	
	· ·	Seal is not securely affixed to the door			X	
1.3	Sharp Edges	Refrigerator component is damaged or missing Sharp edges are present	Χ			
<del>-</del>		Sink or component thereof is missing			X	
		Improperly functioning faucet			X	
1.3	Sink	Sink is not draining Sink is damaged and does not hold water			X	
1.5	SINK	Sink is improperly installed, pulling away from wall,			<u>^</u>	
		there are gaps between the sink and wall, or it is			X	
		leaning				
		Smoke detector not installed in each bedroom or each level within unit	Х			
1.3	Smoke Detector	Smoke detector does not produce audio or visual				
		alarm when tested	Х			
	Sprinkler Assembly	Sprinkler head assembly is obstructed by items or		}	X	
		objects within 18 inches of the sprinkler head Paint or foreign material on sprinkler head				
1.3		assembly			X	
		Sprinkler head escutcheon missing			Χ	
		Concealed sprinkler cover plate assembly is		}	X	
		imissing Treads are missing or damaged			······	
1.3	Stairs	Stringer is damaged			X	
1.3	Structural	Structure has failed or is in danger of failing	X			
1.3	Toilet	:Toilet is missing :Toilet is inoperable	· · · · · · · · · · · · · · · · · · ·	X		
		Toilet is inoperable Toilet seat is broken, loose, or missing	X		Х	
		Toilet is not secured at the base			X	
1.3	Trash Chute	Chute door does not open, self-close, or latch			Χ	
1.3	Trip Hazard	Chute is clogged Trip hazard on walking surface	<b></b>		X X	
٠.٠	IIII IIMZAIG	Temperature and Pressure Relief (TPR) Valve is		· · · · · · · · · · · · · · · · · · ·		
	Water Heater	missing, disabled, blocked, or discharging water	<b>[</b>	X		
		No hot water		X		
1.3		The relief valve discharge piping is improperly installed, incorrect length, terminates less than 2-			Х	
1.3		inches, or incorrect material	<u> </u>	}		
		Chimney or flue piping is misaligned, missing, or	Х			
		blocked	^			
<del>-</del>		Missing safety divider Window will not stay open		X	X	
1.3	Window	Missing or damaged pane or sash			X	
		Weather stripping is damaged or missing			Χ	